

Index
 File No. V-21
 T 2N R. 36E
 Merid. Will


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
 Survey No. _____
 Cor. No. _____

R.D. WALLA WALLA County UMATILLA
 N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE - ORIGINAL POST IS GONE. A POST OF RECENT ORIGIN IS AT APPROXIMATE CORNER POSITION.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIGINAL 6" TAMARACK IS NOW BROKEN OFF AT GROUND LEVEL & IS LYING ON GROUND. FULL SCRIBES VISIBLE, "T2N R36E S26 BT". ROOT HOLE BEARS N50°W, 4°FT. ALL OTHER BT'S ARE GONE.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature Dennis L. Gaylord Title PLS 1636 Division _____ Headquarters _____ Date 7-14-82
 7100-52 (3. 68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ **Title** _____ **Date** _____ **State Registration No.**
or Agency _____

Certified Cor. Record Prepared ? Yes No **Filed At:** _____ **Date** _____

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

Index

File No. V-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 2N R. 36E

R.D. Walla Walla

County Umatilla


Merid. Willamette

N.F. Umatilla

State Oregon

CORNER DIAGRAM Sec.36

DESCRIBE CORNER MONUMENT FOUND



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

Orig. 6" now 6" down Tamarack snag-full scribing present-root hole bears N50W-4.0 ft..
Other BT's gone.

PHOTO IDENTIFICATION DATA

Photo No. 1280-49

Filed At. Umatilla N.F.

Object Ident. two I.P.'s

Ident. By L. D. Bunting
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

From the signed wood post near a gate on Rd.#3128 follow posted line North 2000 feet to corner.

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____
Agency

Signature
Larry D. Bunting

Title
Land Surveyor

Division

Headquarters

Date

6/83

7100-52-(3,68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" Aluminum pipe with a 3" Aluminum cap and a breakaway footplate containing a magnet.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

- 10" Spruce N27W-9.7 ft. scribed T2NR36ES26BT and with a 1" Brass disk stamped PLS 896.
- 14" Spruce S10W-9.9 ft. scribed T2NR36ES35BT and with a 1" Brass disk stamped PLS 896.
- 12" Spruce N62E-17.0 ft. scribed T2NR36ES25BT and with a 1" Brass disk stamped PLS 896.
- 12" Spruce S29E-10.6 ft. scribed T2NR36ES36BT and with a 1" Brass disk stamped PLS 896.

Work Done By Larry D. Bishop Title Surveyor Date 6/83 State Registration No 896
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Set guard posts South and East with signs 54-2 and 54-4.
Nailed 54-4 and BT signs to BT's and painted band and blazes red.