CERTIFIED RECORD OF LAND CORNER MONUMENTATION

	V - 7 DIAGRAM	
	1	1
History of original corner establishment:	T2S R30E	- 1
	1/4 <u>S29</u>	1
The original corner was established by George S. Pershin on	S32	1
September 10, 1878, under GLO contract No. 293, as follows:	PLS 1636	1
	2002	1
Set a stone, 15" x 10" x 8", on west hillside for the 1/4		1
section corner.		

Original corner evidence recovered:

Found the original corner stone firmly set on the west edge of a mound of stones. The corner stone is 16" x 11" x 7" and is plainly marked "1/4" on the north face.

Monument and accessories established to perpetuate the original position of this corner:

In place of the original corner stone, I set a $1" \times 30"$ flared, galvanized iron pipe 22" into the ground. A $2 \frac{1}{2}"$ brass cap attached to the top of the iron pipe is marked as shown in the diagram above. I bury the corner stone along the west side of the pipe and build a mound of stones around the pipe, from which:

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 NE", attached at ground level, bears N38° E, 200.3 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 SE", attached at ground level, bears S43° E, 101.2 feet,

A 5/8" x 24" iron rod, set 22" into the ground with a 3/4" brass washer, marked "PLS 1636 SW", attached at ground level, bears S32° W, 94.4 feet.

A 5/8" x 24" iron rod, set 23" into the ground with a 3/4" brass washer, marked "PLS 1636 NW", attached at ground level, bears N53° W, 108.5 feet.

I hereby certify the above corner point was perpetuated as hereon described on February 13, 2002. Magnetic declination set in compass: 16°E.

PROFESSIONAL LAND SURVEYOR

DENNIS L CAN

Renews June 30, 2003

Recorded at the office of County surveyor, County of Umatilla, State of Oregon, on:

RECEIVED BY

Umatilla County Surveyor

Date 6-02

No. 02-154-R