

Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. UIR Cor. No. 61M.P.

T 2 S. R. 34 E.

R.D. _____ County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



UIR
61M

DESCRIBE CORNER MONUMENT FOUND

2 1/2" DIAM. BRASS CAP SET ON A 2" IRON PIPE
EXTENDING 7" OUT OF GROUND IN A MOUND
OF STONES. CAP MKD. PER SKETCH.
SEE REMARKS FOR TRUE CORNER.

T25
R34E
UIR
61M
1917

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

10" D.B.H. DOUGLAS FIR, N.62°E., (1") 10 LKS., W/HELED FACE.
10" D.B.H. TAMARACK, S.17°E., 19 LKS., W/DOUBLE HELED FACE.
30" HIGH STUMP, NO MARKS, (30" DIAM.) N.62°W., 20 LKS.
ATTACHED BT. TAGS, ATN. SIGNS, PAINTED RED BANDS.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

TAKE ROAD 21 TO WEST LINE OF S. 31, T. 2 S., R. 35 E., TAKE
ROAD NORTH 2.4 MILES TO FOREST BOUNDARY, CORNER IS
ON RT. AND 20'± FROM ROAD.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature Clayton J. Martin Title LAND SURVEYOR Division _____

Headquarters _____ Date 7-11-85

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET STEEL POSTS 4' E N.E.S. OF CORNER W/ATTN., MON., AND PROPERTY BOUNDARY SIGNS ATTACHED.

ACCESSORIES : DESCRIBE NEW BY'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By C. J. MARTIN Title LAND SURVEYOR Date 7-11-85 State Registration No. LS 1910
or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

REMARKS

TRUE 61 MILE CORNER IS A 6" D.B.H. FIR, W/OPEN FACE ON NORTH AND WEST, W/SCRIBING ON BOTH FACES. TRUE CORNER IS 12' (1 LK.), S. 20° W. FROM BRASS CAP WHICH IS A WITNESS CORNER. CORNER TREE HAS ATTN. SIGN, BLAZES AND BAND PAINTED RED.

Index File No. T. 2 S. R. 34 E. M. WILLAMETTE, Tract or Surv. No.

Cor.

01R
/ 61M

Index File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. UIR

Cor. No. MP 61


T 25 R. 34E

R.D. Ukiah County Umatilla

Merid. Will

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found orig. 6" fir alive and squared on west & north sides with scribes. Found brass-capped, iron post, 2" dia, solid in the ground, 8" above surface.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Orig. 7" fir is alive with double, healed blazes and bears N62°E, 7 ft from corner.
 Orig 8" tamarack is alive with double, healed blazes and bears S17°E, 12.5 ft from corner.
 Orig 30" pine is sawn stump with no marks and bears N62°W, 13 ft from corner.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estob. By _____
 Agency _____

Signature

Title

Division

Headquarters

Date

7100-52-(3,68)

Dennis F. Gaylord

PLS 1636

5-24-84

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.