


E-9
H-181

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Restoration of N.E. Cor Sec 8, T3N, R29 E.W.M.

History of original corner establishment:



E-9

Description of corner evidence found: Found stone reset by Oregon State Highway Dept. & marked with sign post.

Description of monument and accessories I established to perpetuate the original location of this corner to 8, 9, 4 & 5 T3N, R29 E.W.M. I set a 1" x 36" galv. pipe with 2 1/2" Brass cap fastened to Top marked:

Umatilla County
Surveyor

T3N R29E

5 | 4
8 | 9

1971



Office of County of
State of, I hereby certify that the within instrument was filed in this office
for record on the day of, 19....., at o'clock m., (signed)
..... by
(COUNTY OFFICIAL) (DEPUTY)