


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Restoration of N.W. Cor Sec 17, T3N, R29E W.M.

History of original corner establishment:

Wood Post set in



Description of corner evidence found:

Found ~~2~~ 1 3/4" iron pipe at corner of 4 fences running in the 4 cardinal directions.

Description of monument and accessories I established to perpetuate the original location of this corner

to 17, 18, 7, 8, T3N, R29E W.M. I set a 2 1/2" Brass cap in the existing Pipe grouted with concrete. Marked

UMATILLA COUNTY SURVEYOR

T3N R29E

7 | 8
18 | 17

1971



Office of..... County of..... State of....., I hereby certify that the within Instrument was filed in this office for record on the day of, 19....., at o'clockm., (signed) by (COUNTY OFFICIAL) (DEPUTY)