


H-180 J-5

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Restoration of N.W. Cor Sec 17, T3N, R29E W.M.

History of original corner establishment:

Wood Post set in



J-5

Description of corner evidence found:

Found ~~3~~ 1 3/4" iron pipe at corner of 4 fences running in the 4 cardinal directions.

Description of monument and accessories I established to perpetuate the original location of this corner

to 17, 18, 7, 8, T3N, R29E, W.M. I set a 2 1/2" Brass cap in the existing Pipe grouted with concrete. Marked

UMATILLA COUNTY SURVEYOR

T3N R29E

7 | 8
18 | 17

1971



Office of..... County of.....
State of....., I hereby certify that the within Instrument was filed in this office
for record on the day of....., 19....., at..... o'clock.....m., (signed)
..... by.....
(COUNTY OFFICIAL) (DEPUTY)