

H-182 N-9

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Restoration of SE cor Sec. 17, T3N, R29E W1

History of original corner establishment:

Wood post set in



N-9

Description of corner evidence found:

Dug & found charcoal at fence corner common to 3 fences going North - East - West.

Description of monument and accessories I established to perpetuate the original location of this corner

to 16, 17, 20 & 21, T3N, R29E. I set 1" x 36" galv. Pipe with 2 1/2 Brass Cap fastened to top and marked;

Umatilla County Surveyor

T3N R29E

17 | 16
20 | 21

1971



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19....., at..... o'clock.....m., (signed)

..... by..... (COUNTY OFFICIAL) (DEPUTY)