

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
 Umatilla County Surveyor's Office

SECTION 20	TOWNSHIP 3N	RANGE 36E
COUNTY: Umatilla		DATE 6/20/08
CORNER DESIGNATION: O-7 Center North 1/16 Section 20		(Please check one) <input checked="" type="checkbox"/> Condition Report Only <input type="checkbox"/> Not Found <input type="checkbox"/> Renewed <input type="checkbox"/> Unrecorded <input type="checkbox"/> Surveyed In <input type="checkbox"/> Referenced Out
Previous Renewals / Surveys, etc. U.S. Indian Services Surveyor C.E. Redfield set an iron post in 1919.		
Monument(s) & Accessories Found: (Condition & Source) Found a 2" galvanized iron pipe with a 2 1/2" brass cap protruding 17" on an open southeast slope.		
Monument Detail:	Sketch:	
Monument Set (Procedures and Description):		
New Accessories: Rebuilt stone mound		
Location & Comments: Monument is located on a steep open southeast slope.		Compass Declination:
Firm / Agency USKH Inc. Address: 5 N. Colville St. Walla Walla, WA 99362 Party Chief Greg E. Flowers		SURVEYOR'S SEAL
Notes		
Witness Damon Locke		

RENEWS/2 13/1 09
6/30/08

D8-112-c