


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

N-12

History of original corner establishment:
None



Description of corner evidence found:
None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2 1/2" by 28" aluminum pipe, with 3 1/4" aluminum cap, 22" in the ground, marked as shown, from which:

23" Ponderosa Pine, bears N. 52 3/4° E., 25.3 feet scribed "E1/16 S16" "BT" on double blaze with 3/4" brass washer "RLS 2308" nailed to the lower blaze.

28" Douglas Fir bears N. 5° W., 28.1 feet, scribed "E1/16 S16" "BT" on double blaze with 3/4" brass washer "RLS 2308" nailed to the lower blaze.



DATUM: NAD83(1991)
STATE PLANE COORDINATES: Oregon North Zone in International Feet

Latitude	Longitude	Northing(y)	Easting(x)
45°43'48.57795" North	118°11'46.01030" West	760695.526	8790346.336

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A. Schlaich

OREGON
JULY 16, 1987
DAVID A. SCHLAICH
2308

RENEWAL DATE: 06/30/2006

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 20.....

..... by.....
(COUNTY OFFICIAL) (DEPUTY)