

USDA-FOREST SERVICE

Index  
File No. R-5

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_

Cor.  
No. \_\_\_\_\_

T 3N R. 38E

R.D. WALLA WALLA

County UMATILLA


Merid. WILLAMETTE

N.F. UMATILLA

State OREGON

CORNER DIAGRAM

T3N R38E



DESCRIBE CORNER MONUMENT FOUND

STONE SET SOLIDLY IN GROUND - TIPPED TO NORTH. STONE IS PLAINLY MARKED WITH 2 GROOVES ON SOUTH FACE AND 5 GROOVES ON EAST FACE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

THERE IS A MOUND OF STONES 3 FEET WEST OF THE CORNER.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLACED A LOCATOR'S SIGN ON A 7" FIR S10°W, 20 FEET FROM CORNER. THIS SIGN IS ON SOUTH SIDE OF TREE & IS VISIBLE FROM RIDGE TOP - WHICH IS ABOUT 30 FEET SOUTH OF CORNER.

*Signature*

*Title*

*Division*

*Headquarters*

*Date*

FS-7100-52 (3/68)

*Dennis J. Hayford* PLS 1636 9/9/97

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

277 FEET NORTH OF THIS CORNER IS A 32" WESTERN LARCH - B.T. FOR THE SUPERCEDED CORNER SET IN 1899, I OPEN 12" OF OVERGROWTH WOOD & FIND SCRIBES. THIS TREE WAS S1°W, 115 1/2 FEET FROM OLD, 1899 CORNER. ORIGINALLY A 9" TAMARACK - WELL HEALED SCAR.

12

Index: File No. T. R. M. Tract or Surv. No. Cor.

13

R-5 T3N R38E