

Index
File No. G-9

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. Cor.
No.

T 3S R. 33E R.D. Ukiah County

Merid. Will. N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

There was originally a post - Gone

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND - A ponderosa pine 24" DBH for section 8 bearing N39 degrees W 27 links distance has a visible scar on it, good condition. This tree has a sizable fire scar on the uphill side. A western larch 21" DBH for section 17 bearing S35 degrees W 59 links distance has a good scar indicating a scribed face. Both trees I attached a bearing tree sign on facing corner & put an attention sign on the back. Both trees. I painted a six inch red band around & also painted scribed faces red. All over the corners we looked for or found, we used a compass, photos, contour maps or anything else we thought would help

PHOTO IDENTIFICATION DATA

Photo No.

Filed At.

Object Ident.

Ident. By Tags & Paint

Signature

PLANE COORDINATE POSITION DATA

State Zone

X

Y

Estab. By

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

us find them including GLO holes, etc.

Signature
MLC & DDM

Title
Forestry Tech.

Division

Headquarters

Date
10/11/79

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No.