

Index
File No. J-5


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. Cor.
No.

T 3S R. 33E R.D. County

Merid. N.F. State

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Material: Stone Size: 16'x8"x 5"
Height Above Ground: All flat on ground
Condition: Fair
Markings: Three faint notches can be seen. Painted stone red

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 39" ponderosa pine for section 8 bearing N37 degrees E 31 lks distance is in good condition. A dead douglas fir snag about 5½' tall 10" DBH bearing S17 degrees W 60 lks distance has good scribing showing. A dead fallen over douglas fir tree 11" DBH bearing S68 degrees E 26 lks distance has a good scribing showing. All of the trees I attached a bearing tree tag on the corner side & an attention sign on the back. Painted scribing & put as

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

six inch red band in paint on all of them.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By Tags & Paint
Signature

PLANE COORDINATE POSITION DATA

State Zone
X
Y
Estab. By
Agency

Signature Title Division Headquarters Date
MLC & DDM Forestry Tech. 10/11/79 7100-52-(3/68)

2
6
7
4
5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. _____