

Index File No. F-25

CORNER RECORD (SEARCH)

(Ref. FSM 7 151.4)

Tract or Survey No. \_\_\_\_\_

Cor. No. F-25


T 4 N R. 37 E

R.D. \_\_\_\_\_ County \_\_\_\_\_

Merid. \_\_\_\_\_

N.F. \_\_\_\_\_ State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Searched by Boise-Cascade (La Grande)  
Brass cap found.  
~~No card furnished to us.~~



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

D Fir 30" DBH N 19 1/2° E 38 IKS  
W Fir 26" DBH N 45 1/2° W 39 IKS

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_

*Signature*

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_

*Agency*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

TGJ RM

Title

Forester

Division \_\_\_\_\_

Headquarters \_\_\_\_\_

Date

1/77

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At \_\_\_\_\_ Date \_\_\_\_\_

11

REMARKS

12

Index File No. \_\_\_\_\_ Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_

13

USDA-FOREST SERVICE

INDEX  
 FILE NO. T-1  
 T. 4 N R. 38 E R.D. Walla Walla County Umatilla  
 Merid. Willamette N.F. UMATILLA State Oregon

CORNER DIAGRAM

1 DESCRIBE CORNER MONUMENT FOUND  
 1 1/4 1 Found standard GLO brass cap stamped as shown in diagram.  
 1 S25 | S30 1  
 N 1939 1  
 1 1  
 1 2

1 DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
 1 A 24" dbh White Fir with healed blaze bears N39°W, 25.9'.  
 PHOTO IDENTIFICATION DATA 1 A 30" White Fir with healed blaze bears N22°E, 26.2'.  
 Photo No. 1 A 22" White Fir bears S57°E, 40.2' scribed T4N R38E S30 BT.  
 Filed At. 1 A 15" White Fir bears S59°W, 58.1' scribed T4N R37E S25 BT.  
 Object Ident. 1 A steel fence post with land survey marker sign is 3' north.  
 Ident. By 1  
 Signature 71 3

PLANE COORDINATE POSITION DATA

1 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
 State Zone 1 The corner may be reached by traveling Highway 204 west from the Tollgate Store 1.2 mile to  
 X 1 a sharp curve turning from northwest to southwest at the bottom of the hill. An opening is  
 Y 1 just west of some cabins to the north. Go 600' north down a steep hill near these cabins.  
 Estab. By 1 The corner is under the east edge of a small ridge which protrudes out from the steep hill.  
 Agency 81 4

Signature Title Division Headquarters Date FS-7100-52 (3/68)  
 Surveyor Pendleton, OR 9-04-65 5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Cleared brush and debris away from corner.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None set.

10

Work Done By, David L. Haddock Title Land Surveyor Date 8-15-95 State Registration No. PLS 852  
Certified Cor. Record Prepared? Yes  No  or Agency PLS 852 Filed At: \_\_\_\_\_ Date 11

REMARKS

12

Index File No. T-1 T. 4 N. R. 38 E. N. Willamette Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_ 13