

Index
File No. W 1/2 - 6

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____

Cor.
No. W 1/2 - 6


T 4 N R. 38 E

R.D. Walla Walla County Vmatilla

Merid. Willamette

N.F. Vmatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

3/4" X 24" Iron Pipe

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

Title

Division

Headquarters

Date

7100-52-(3/68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____ 11

REMARKS

3/4" x 24" Iron pipe set by D.L. Staebler ~~1974~~¹⁹74 (ORLS)

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13