


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T4N R38E

History of original corner establishment:

None. This corner was established and monumented as part of this survey.



Description of corner evidence found:

Not applicable.

Description of monument and accessories established to perpetuate the original location of this corner:

At position determined by survey, set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap, 24" in the ground surrounded with a mound of earth and stone. Set steel fence posts North and Southeast of corner. Attached sign 54-2 to both posts and 54-4 to one post. Monument cap is marked as shown in diagram.

New bearing trees:

A 23" Douglas fir bears N 50° E, 13.3 feet, scribed COR 1 TR061411 BT-BT on double blaze.

An 11" white fir bears S 44° E, 7.2 feet, scribed COR 1 TR061411 BT-BT on double blaze.

Attached brass washer stamped "PLS 1106" to bottom of blaze on each bearing tree. Attached sign 54-3 and 54-4 to each bearing tree and painted face of blaze and a 6" red band around each bearing tree.

Compass declination: 18° East

Witnesses:

Jason Wells, LSIT  
Mark Hammersla

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

renews 6-30-02

Office of County Surveyor County of Umatilla  
State of Oregon I hereby certify that the within instrument was filed in this office  
for record on the ..... day of ..... 19.....

(COUNTY OFFICIAL)


(DEPUTY)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T4N R38E

History of original corner establishment:

None. This corner was established and monumented as part of this survey.



Description of corner evidence found:

Not applicable.

Description of monument and accessories established to perpetuate the

original location of this corner:

At position determined by survey, set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap, 24" in the ground surrounded with a mound of earth and stone. Set steel fence posts North and Southeast of corner. Attached sign 54-2 to both posts and 54-4 to one post. Monument cap is marked as shown in diagram.

New bearing trees:

A 23" Douglas fir bears N 50° E, 13.3 feet, scribed COR 1 TR061411 BT-BT on double blaze.

An 11" white fir bears S 44° E, 7.2 feet, scribed COR 1 TR061411 BT-BT on double blaze.

Attached brass washer stamped "PLS 1106" to bottom of blaze on each bearing tree. Attached sign 54-3 and 54-4 to each bearing tree and painted face of blaze and a 6" red band around each bearing tree.

Compass declination: 18° East

Witnesses:

Jason Wells, LSIT  
Mark Hammersla

REGISTERED PROFESSIONAL LAND SURVEYOR
---

*William R. Wells*

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
---

*Renews 6-30-01*

Office of Survey County of Umatilla

State of OR I hereby certify that the within instrument was filed in this office for record on the ..... day of ..... 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

*T4N R38  
7*

*01-149-B*