

Index
File No. F-25

CORNER RECORD (SEARCH)

(Ref. FSM 7 151.4)

Tract or
Survey No. _____

Cor.
No. F-25


T 4 N R. 37 E

R.D. _____ County _____

Merid. _____

N.F. _____ State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Searched by Boise-Cascade (La Grande)
Brass cap found.
~~No card furnished to us.~~



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

D Fir 30" DBH N 19 1/2° E 38 IKS
W Fir 26" DBH N 45 1/2° W 39 IKS

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

TGJ RM

Title
Forester

Division _____

Headquarters _____

Date

1/77

7100-52 (3/68)

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

11

REMARKS

12

Index File No. _____ Tract or Surv. No. _____ Cor. _____

13

USDA-FOREST SERVICE

INDEX
 FILE NO. T-1
 T. 4 N R. 38 E R.D. Walla Walla County Umatilla
 Merid. Willamette N.F. UMATILLA State Oregon

CORNER DIAGRAM

1 DESCRIBE CORNER MONUMENT FOUND
 1 1/4 1 Found standard GLO brass cap stamped as shown in diagram.
 1 S25 | S30 1
 N 1939 1
 1 1
 1 1

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

1 A 24" dbh White Fir with healed blaze bears N39°W, 25.9'.
 PHOTO IDENTIFICATION DATA 1 A 30" White Fir with healed blaze bears N22°E, 26.2'.
 Photo No. 1 A 22" White Fir bears S57°E, 40.2' scribed T4N R38E S30 BT.
 Filed At. 1 A 15" White Fir bears S59°W, 58.1' scribed T4N R37E S25 BT.
 Object Ident. 1 A steel fence post with land survey marker sign is 3' north.
 Ident. By 1
 Signature 71

PLANE COORDINATE POSITION DATA

1 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 State Zone 1 The corner may be reached by traveling Highway 204 west from the Tollgate Store 1.2 mile to
 X 1 a sharp curve turning from northwest to southwest at the bottom of the hill. An opening is
 Y 1 just west of some cabins to the north. Go 600' north down a steep hill near these cabins.
 Estab. By 1 The corner is under the east edge of a small ridge which protrudes out from the steep hill.
 Agency 81

Signature Title Division Headquarters Date FS-7100-52 (3/68)
 Surveyor Pendleton, OR 9-04-65

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
Cleared brush and debris away from corner.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
None set.

10

Work Done By, David L. Haddock Title Land Surveyor Date 8-15-95 State Registration No. PLS 852
Certified Cor. Record Prepared? Yes No or Agency PLS 852 Filed At: _____ Date 11

REMARKS

12

Index File No. T-1 T. 4 N. R. 38 E. N. Willamette Tract or Surv. No. _____ Cor. _____ 13