

Index
File No. J-5

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ No. _____

T 4S R. 30E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM

T4S R30E

S 7 | S 8

S 18 | S 17

1981

PLS 848



DESCRIBE CORNER MONUMENT FOUND

Found 14x11x10 stone with 4 notches on South face and 5 notches on the East face, set in a mound of stone in E-W fence line.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

No bearing trees originally established.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At: _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is in E-W fence line in open ground on a gentle SE slope.

An E-W primitive road runs just South of the corner.

Signature

Title
PLS 848

Division

Headquarters: _____

Date

7100-52-(3/68)

Mt. Vernon, OR

9/10/81

5

CORNER RECORD (PERPETUATION)

GPO 902-673

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 16 inches in the ground and raised a mound of stone and earth around the pipe.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

No bearing trees available.
Set steel posts with warning signs 6 ft. East and 6 ft. West from corner.

10

Work Done By D.M. Ferguson Title Surveyor Date 9/10/81 State Registration No. or Agency OR PLS 848

Certified Cor. Record Prepared? Yes No Filed At: Umatilla Co Surveyor's Off Date

11

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REMARKS

Witnesses to above corner:
D. Mitchell Ferguson
Mike Woodward

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

12

USDA-FOREST SERVICE

Index File No. J-5

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-5

T 45 R. 30E R.D. Ukiab County _____

Merid. _____ N.F. _____ State _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone, Approx. Call Size. 4 notches on South edge. 5 notches on east edge. Stone sits loose at east edge of small stone mound. Mound sits at east edge of triple-post rock Jack in fence.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None. No trees available originally. I feel sure the stone is the original, however the mound may not be in the original position. I did not dig under the mound for traces of the corner post.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

fence runs east-west.
 A primitive road follows along south side of fence.
 I placed a location poster on a post of the rock Jack.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature _____ Title _____ Division _____ Headquarters _____ Date _____

T. Hollamby

4-17-80 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. _____
U.S. G.P.O. 1977-725-576/586