

Index

File No. C-17


CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_ No. C-17T 4S R. 32ER.D. Ukiah County UmatillaMerid. Will.N.F. Umatilla State Oregon

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

None

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 32" Douglas fir with good scars on it. Scribing is overgrown. Tree is rotten and probably will fall down in near future. This tree is painted with 6" red band and put proper tags on it. Tree bears west 9 lks from corner. Put a steel post up about 10' east of tree with proper tags attached.

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*Signature  
MLCTitle  
For, Tech,Division  
USFSHeadquarters  
UkiahDate  
5/31/78

7100-52-(3,68)