

USDA-FOREST SERVICE

Index File No. C-3

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. C1/4


T 4S R. 32E

R.D. Ukiah County Umatilla

Merid. W.M.

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None set.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None set.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is about 100 feet north of the main Forest Service road through Granite Meadows. Visible from the road.

Signature

Beverly B. Barbour

Title
P.L.S.

Division

Headquarters

Date
11/9/77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

At surveyed point set 2 1/2"x30" galvanized pipe with brass cap marked:
Set pipe 8" to bedrock and a mound of stone around.

T4S R32E
C1/4 S6
OR PLS 1051
1977

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A pine 36" in dia. bears S88°E, 60.6 feet, scribed C1/4 S6 BT. A pine 36" in dia. bears S53°W, 39.9 feet, scribed C1/4 S6 BT. Placed 54-3s and 54-4s on trees, brass washer on BT blazes, stamped PLS 1051. Placed 54-4 and 54-9 on fence post 4' east of corner. Painted 6" red band and painted both blazes red.

10

Work Done By B.B. Barbour Title P.L.S. Date 11/9/77 State Registration No. or Agency OR PLS 1051

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

Witnesses to the above: D.L. Landers, S. Nelson

12

Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. _____

13