

Index

File No. T-25

## CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or  
Survey No. \_\_\_\_\_Cor.  
No. \_\_\_\_\_

87

T 5 S. R. 30 E. R.D. Ukiah County UmatillaMerid. Willamette N.F. Umatilla State Oregon

## CORNER DIAGRAM



## DESCRIBE CORNER MONUMENT FOUND

Stone mound, 3' diam., 10" deep, 10" above ground; good condition.

Mound consists of 7 or 8 stones. I cannot distinguish corner stone.

*Monumented By BLM, 1978*

## DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 24" ponderosa pine bears S.8°E., approx. 50 ft. It has old healed blaze facing corner and a line blaze (X) facing corner. I tagged it as a B.T., but it could be only a line tree.

A 24" ponderosa pine bears N.82°W., approx. 25 ft. Scribing visible. Has 1969 location poster. Tree blazed on 4 sides. Tree broken off about 30 ft. high, but is still alive (green limbs).

## PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

*Signature*

## PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

*Agency*

Signature

T. Hollamon

Title

Eng, Tech,

Division

Headquarters

S.O,

Date

4/24/74

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed a location poster on a 5" ponderosa pine on west side of road,  
approx. 150 ft. east.

I placed blank B.T. tags on the B.T.'s

10

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No.  
or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_ 11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13