

Index File No. V-10

CORNER RECORD (SEARCH)
(Ref. FSM 7.151.4)

Tract or Survey No. _____ Cor. No. _____


T 55 R. 32E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set, 2½ ins. diam., in a mound of stone, 3 ft. base, to top, with brass cap mkd.

U.S. Dept. of Interior
Bureau of Land Management

W 1/16 $\frac{S\ 28}{S\ 33}$
1980

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Douglas Fir, 8 ins. diam., bears N. 89° E., 121½ lks. dist.,
A Ponderosa Pine, 15 ins. diam., bears S. 60½° E., 70½ lks. dist.,
BT's in good condition with scribing visible on unhealed single blaze.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner of fences N & E is 10' East.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Ray D. Knight
Signature

Title LS 1099 Division _____ Headquarters _____ Date 9-17-84

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency

Certified Cor. Record Prepared? Yes (No) Filed At: Date

REMARKS

Index File No. V-10 T. 5S R. 32E M. WILLAMETTE Tract or Surv. No.

Cor.