

Index
File No. X-12

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or Survey No. _____ Cor. No. _____


T 5S R. 32E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set, 2½ ins. diam., in a mound of stone, 3 ft. base, to top, with brass cap mkd.

U.S. Dept. of Interior
Bureau of Land Management

E 1/16
C S 33 C
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Douglas Fir, 7 ins. diam., bears N. 20° E., 18 lks. dist.,
A Douglas Fir, 10 ins. diam., bears S. 3° W., 14 lks. dist.,
Both BT's found to be in good condition.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Agency

Say Douglas

Title

LS 1099

Division

Headquarters

Date

9-17-84

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

10

Work Done By: Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. X-12 T. 5S R. 32E M. WILLAMETTE Tract or Surv. No. _____ Cor. _____

13