

USDA-FOREST SERVICE

Index

File No. C-20

T 5S

R. 33E

Merid. WM

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. NF John Day

County _____


N.F. Umatilla

State OR

Tract or Survey No. _____

Cor. No. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Set a 2 1/2" x 30" alum pipe w/a 3" alum. cap
 marked E 1116
 C-C
 S2
 PLS 1832
 1984

Built a stone mound
 around monument

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

a lodgepole, 10" dia N83°45'E, 184.3 ft marked CE 1116 S2 BT
 a P. Pine, 17" dia, S41°E, 205.3 ft marked CE 1116 S2 BT

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Title

Division

Headquarters

Date

7100-52 (3, 68)

ls/ Fayette S. Munro

sn

PLS 1832

9/13/84

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.