

# GOVERNMENT CORNER RECORD

Township 6N Range 35E Section 35 County UMATILLA  
 State OREGON Date 10/1/96 Number Y-19

Corner Designation : CENTER S 1/16

- Condition Report Only
- Not Found
- Renewed
- Surveyed In
- Referenced

Previous Renewals \_\_\_\_\_

Monument (s) Found: (Condition and Source)

FOUND 3" BRASS MONUMENT IN MONUMENT WELL  
.23' DEEP IN GOOD CONDITION.  
(SEE MONUMENT DETAIL)

### MONUMENT DETAIL

Found  Set

Accessories Found:

NONE



Monument & Accessories Set (Procedure and Description)

SET P.K. NAIL AND ALUMINUM TAGS IN POWER POLES EAST & WEST OF MONUMENT.  
TIED TO CORNER OF IRRIGATION STRUCTURE NORTHWEST OF FOUND MONUMENT.  
(SEE SKETCH DETAIL)

<p style="text-align: center;"><u>Sketch of Monument, Accessories and General Area</u></p>	<p style="text-align: center;">Surveyor's Seal</p> <div style="border: 1px solid black; padding: 5px; text-align: center;">                 REGISTERED                  PROFESSIONAL                  LAND SURVEYOR  <i>Danny K. Cummings</i>                  10/3/96             </div> <div style="border: 1px solid black; padding: 5px; text-align: center;">                 OREGON                  JAN. 21, 1988                  DANNY K. CUMMINGS                  2316             </div> <p>RENEWAL DATE : 12-31-97</p> <p style="text-align: center;">GASCHLER &amp; CUMMINGS</p> <p>Agency _____                  Party Chief <u>D. CUMMINGS</u>                  Notekeeper <u>L. KING</u>                  Witness(s) _____                  Field Book #0-135 pg8-9</p> <p style="text-align: center;">COUNTY SURVEYOR RECORDING INFO</p> <p>Received _____                  Filed _____                  Survey No. <u>96-164-B</u>                  Drawing No. _____                  Index No. _____</p>
--	---