

OREGON CORNER RESTORATION FORM

Section: 36

Township: 6 North

Range: 37 East

County: Umatilla

Date: August 21, 2001

Corner Designation: v-22.125

N.W. corner of West 1/2, East 1/2, N.E. 1/4, N.W. 1/4, Sec. 36

Previous Renewals/Surveys, etc.:

None

Monument(s) & Accessories Found (Condition & Source):

None

Monument Detail:

Monument Set (Procedures & Description):

5/8"x30" rebar with yellow cap stamped "Tomkins Surveying" set at proportioned position along North line of Section 36.

New Accessories:

- 1) Fence post and sign 0.5' North
- 2) 15" White Fir scribed "BT", sign attached bears N 89°W 44.6'
- 3) 13" White Fir scribed "BT", sign attached bears N 62°E 8.7'

Location & Comments:

50' East of major access road

Compass Declination:

19° East

Firm/Agency: Tomkins Land Surveying, Inc.

20 E. Poplar, Suite 204

Walla Walla WA 99362

Party Chief: Paul Tomkins

Notes:

Witness: Josh Davin

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Paul W. Tomkins

OREGON
JULY 26, 1988
PAUL W. P. TOMKINS
2360

*renews 6/30/02
8/21/01*

RECEIVED BY

Umatilla County Surveyor

Date 8-01

Rec'd By JK

No. 01-132-C