

OREGON CORNER RESTORATION FORM

Section: 36

Township: 6 North

Range: 37 East

County: Umatilla

Date: August 21, 2001

Corner Designation: x-23.5

S.E. corner of West 1/2, S.W. 1/4, N.E. 1/4, Sec. 36

Previous Renewals/Surveys, etc.:

None

Monument(s) & Accessories Found (Condition & Source):

None

Monument Detail:

Monument Set (Procedures & Description):

5/8"x30" rebar with yellow cap stamped "Tomkins Surveying" set at protracted position within Section 36.

New Accessories:

- 1) Fence post and sign 0.3' West
- 2) 10" White Fir scribed "BT", sign attached bears N 87°W 10.1'
- 3) 18" White Fir scribed "BT", sign attached bears S 26°E 9.6'

Location & Comments:

Corner falls approximately 75' West of old road.

Compass Declination:

19° East

Firm/Agency: Tomkins Land Surveying, Inc.

20 E. Poplar, Suite 204


Walla Walla WA 99362

Party Chief: Paul Tomkins


Notes:

Witness: Josh Davin

Surveyor's Seal



*Paul W. P. Tomkins*



*renews 6/30/02*

*8/2/01*

RECEIVED BY

Umatilla County Surveyor

Date 8-01

Rec'd By JK

No. 01-132-c