

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

No. $\frac{1}{4}$ Cor

Index
File No. C-5


T 6S R. 30E.

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner is approximately 200' East of U.S.F.S. 5327 Road.
Location tag on East side of Road.

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Signature

Title

PLS

Division

346

Headquarters

9/79

Date

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 32" X 2" flanged iron pipe with brass cap marked:

T6S R30E

 $\frac{1}{4}$

S6|S5

1979

PLS 346

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Douglas Fir, 7" Dia., BRS. S84 $\frac{1}{4}$ °E., 33.9 Ft. Distance.

Douglas Fir, 19" Dia., BRS. N30°W., 37.7 Ft. Distance.

6' Iron Fence Post with "Survey Monument" sign within 5' of Corner.

10

Work Done By Wayne O. Harris Title PLS Date 9/79 State Registration No. 346
or AgencyCertified Cor. Record Prepared? YES ~~XXX~~ Filed At: Umatilla Co. Surveyor Office Date

11

REMARKS

Index File No. C-5 T.6S R.30E W. M. Tract or Surv. No. Cor $\frac{1}{4}$ 6|5

12

13