

Index
File No. G-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ No. _____


T 6S R. 30E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

28" PINE WEST 54.8' SCRIBING VISIBLE

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

THERE IS A LOCATION TAG APX. 400' SOUTH OF CORNER ON OLD ROAD. CORNER IS ON NORTH SIDE OF CREEK IN SMALL RAVINE.

Signature

H. O. Harris

Title

Division

Headquarters

Date

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 2"x30" IRON PIPE WITH BRASS-CAP MARKED: T&S R30E

MONUMENT IS SET IN A MOUND OF STONES.

1/4
S11 S12

1978

PLS 346

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

14" FIR S78E 16.0' MARKED: 1/4 S12 BT.

THE BT'S HAVE A RED-PAINTED STRIPE, BEARING TREE SIGNS, AND AN ATTENTION SIGN. THE NEW BT HAS A BRASS WASHER STAMPED PLS 346 NAILED TO THE LOWER BLAZE. THERE IS A STEEL FENCE POST ON LINE WITHIN 5' OF THE CORNER.

10

Work Done By. W.O. HARRIS

Title _____

Date _____

State Registration No. _____
or Agency

PLS 346

Certified Cor. Record Prepared? Yes

No

Filed At: _____

Date _____

11

REMARKS

12

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

13


Index

File No. G-212
CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____Cor.
No. _____T 6S R. 30ER.D. UkiahCounty UmatillaMerid. WillametteN.F. UmatillaState Oregon

CORNER DIAGRAM



Brass Cap 1978

DESCRIBE CORNER MONUMENT FOUND

NONE. Evidence of Cat tracks where corner would be,
(in small ravine).

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 27' Pond. Pine with blazes and faint scribing on East face.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Location is approx. 100' North of stream and 500' North of
sharp curve in primitive road.

Signature

T. HOLLAMON

Title

ENG. TECH.

Division

Headquarters

Date

5/9/78

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Placed a blank B,T, tag and an attention poster on the B.T.

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor.

13