

USDA-FOREST SERVICE

Index

File No. T-15

T6S

R32E

Merid. Willamette

R.D.

N.F.

CORNER RECORD (SEARCH)

Ref. FSM 7151.4

North Fork John Day

Umatilla

Tract or

Survey No

County

State

Cor.

No.

Umatilla

Oregon

x ----- 1

Corner Diagram

C1/4 S27

1968

1 Describe corner monument found
 1 Standard BLM brass cap stamped as shown in the corner diagram in a mound
 1 of stone.

x ----- 1

Photo Identification Data

Photo No.

filed at

Object Ident.

Ident. by

Signature

1 Describe bearing trees or other official accessories found
 1 A 15" Ponderosa Pine bears N41 E, 43.1'.
 1 A 12" Ponderosa Pine bears S35 W, 63.3'.

x ----- 1

Plane Coordinate Position Data

State

Zone

X

Y

Estab. by

Agency

1 Describe corner location relative to near-by features, also how to reach corner
 1 From the junction of roads 55 and 5506, follow road 55 0.3 miles east to road
 1 070. Follow this road 0.1 miles north to a road not shown on the map which goes
 1 west. Follow this road west 0.1 miles to where the center one quarter corner is
 1 plainly visible about 100' south of the road.

x ----- 1

Signature

Title

Division

Headquarters

Date

7100.52

David L. Handlock Land Surveyor

Pendleton, OR

July 1988

CORNER RECORD (PERPETUATION)

X _____ X
 Monument: Describe new monument set, or work done to preserve existing monument

None

x _____ x
 Accessories: Describe new BT's witness objects etc. established, or work done to preserve existing evidence

Made bands around trees and painted bands and scribe blazes red.

x _____ x

Work done by	David L. Haddock	Title	Land Surveyor	Date	July 1988	State Registration No.	852
Certified cor. record prepared?	yes		no x	Filed at		or Agency	
						Date	

x _____ x
 REMARKS

x _____ x

Index File No.	T-15	T. 6S.	R. 32E.	M. Willamette	Tract or Survey No	Cor.
----------------	------	--------	---------	---------------	--------------------	------

USDA-FOREST SERVICE

Index File No. T-15

T 68 R. 32E

Merid. W.M.

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. N. Fk. J. Day County Umatilla

N.F. Umatilla State Or.

Tract or Survey No. _____

Cor. No. _____

CORNER DIAGRAM



$0\frac{1}{2}$ S27

DESCRIBE CORNER MONUMENT FOUND

$2\frac{1}{2}$ " iron pipe with brass cap mkd.

$0\frac{1}{2}$ S27
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

P. Pine, 11", S35°W, 63.0', with healed blaze
P. Pine, 11", N41°E, 42.9', " " "

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner falls on flat south of 075 rd. and visible from rd.

Signature
F. L. Munro

Title
L.S.

Division

Headquarters

Date
11/19/68

FS-7100-52 (9/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None.

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

BT's have blaze and 6" band painted red, BT tags and "Land Survey Monument" signs. 6' steel fence post with "Land Survey Monument" sign within 5' of the corner.

10

Work Done By F.S. Munro Title L.S. Date 11/1/86 State Registration No. 1832
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T-15 T. 68 R. 32E M. W.M. Tract or Surv. No. _____ Cor. _____

13