

Index File No. A-25

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 6S R. 32E


R.D. UK19h County _____

Merid. _____

N.F. _____ State _____

CORNER DIAGRAM

on 1/84



DESCRIBE CORNER MONUMENT FOUND

Brass Cap!

*T 5S R 32E
S 36
51 56
R 32E R 33E
T 6S
CC
1968*

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

See monumentation file

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature

T. Hollamon

Title

Division

Headquarters

Date

2/75

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By. _____ **Title** _____ **Date** _____ **State Registration No. or Agency** _____

Certified Cor. Record Prepared ? Yes No **Filed At:** _____ **Date** _____ **11**

REMARKS

12

Index File No. **T.** **R.** **M.** **Tract or Surv. No.** **Cor.** **13**

Index
File No. A-1

CORNER RECORD (SEARCH)
(Ref. FSM 7.151.4)

Tract or
Survey No. _____
Cor. No. _____


T G S R. 33 E

R.D. UKIAH County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found the 1980 BLM corner tree, an 8" White Fir, alive with unhealed blazes, markings as described, from which:

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

The 1980 BLM bearing trees:
A 6" White Fir, alive and in fair condition, with well-healed single blaze bears S 43°E 19.1 feet;
An 8" White Fir, alive and in fair condition with well-healed single blaze bears S 69°W 19.1 feet.
The 1980 BLM Reference Monument was not found.

PHOTO IDENTIFICATION DATA

Photo No. 280-232
Filed At. UMATILLA NAT. FOR.
Object Ident. Direct
Ident. By S. J. [Signature]

We find the following described reference monument, extending 10" above ground, with aluminum cap marked:

U.S. Dept. of Interior
Bureau of Land Management
14.5 ft. RM
T6S R32E
S1 CC
1982

Which bears S 45°W 13.2 feet from the corner tree.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Title LS 1099 Division _____ Headquarters _____

Date 9-17-84

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

10

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: UMATILLA Co. SURVEYOR Date 9-84

11

REMARKS

Corner is located in dense stand of Fir and Larch. Corner of fences N-S and W bears approx. 5 ft. West and 20 feet North.

August 14, 1984

12

Index File No. A-1 T. 6S R. 33E M. WILLAMETTE Tract or Surv. No.

Cor.

13