


Index File No. E-21
T 6 S. R. 33 E.
Merid. Will.

CORNER RECORD (SEARCH)

Tract or Survey No. _____
Cor. No. E-21

R.D. UKIAH County UMATILLA
N.F. UMATILLA State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone 12" x 8" x 8", 6" Above ground AND in good condition. No MARKINGS were found.

Brass Cap! See Mon. File.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

28" D.B.H. Pond. Pine brs. N. 65° E. 41 lks. - good cond.
30" D.B.H. Pond. Pine brs. S. 27° E. 44 lks. - good cond.
29" D.B.H. Pond. Pine brs. N. 69° W. 66 lks. - good cond.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Signature

Title

Division

Headquarters

Date

7100-52

Melvin Christian Forestry Tech.

UKIAH

2-17-71

REV. '65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. E-21 T. R. M. Tract or Surv. No. Cor.