


Index
 File No. E-7
 T GS R. 33 E
 Merid. WILLAMETTE

CORNER RECORD (SEARCH)
 (Ref. FSM 7.151.4)

Tract or
 Survey No. _____ Cor. No. _____

R.D. UKIAH County UMATILLA
 N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found the remains of the original SE bearing tree, an 18" Engleman Spruce, dead and down, we open and find good scribing "1/4 S"
 No evidence of the corner stone or orig. NE bearing tree was found.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____

Agency
 Signature *Ray D. Douglas*

Title LS 1099 Division _____ Headquarters _____ Date 9-17-84 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

The original corner position is determined at record bearing and distance from the standing position of the original SE bearing tree.

T6S R33E
1/4 S 5
S 8

At the corner position, we set a 2"x30" galvanized iron pipe, 22 inches in the ground and in a 2 ft. diameter mound of stone, with brass cap attached, marked:

PLS 1099
1984

ACCESSORIES: DESCRIBE NEW B.T.'s, WITNESS OBJECTS ETC, ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

The original SE bearing tree, an 18" Engleman Spruce, dead and down, bears S 58°E 6.6 feet. And new bearing trees:
An 8" Engleman Spruce, scribed "1/4 S5 BT" on a double blaze bears N 59°E 33.3 ft.
A 10" Grand Fir, scribed "1/4 S 8 BT" on a double blaze, bears S 49°E 52.6 ft.
Attached brass washer marked "LS 1099" to lower blaze of each new bearing tree.

10

Work Done By: Gary Langlitz Title: LS 1099 Date: 8-84 State Registration No. or Agency

Certified: Cor. Record Prepared: Yes No Filed At: UMATILLA CO SURVEYOR Date: 9-84

11

REMARKS

Corner is located in E-W fenceline, approx. 15' West of Creek, course North.
Compass Declination
Steel Tape
August 1, 1984.

12

Index File No. E-7 T. 6S R. 33E M. WILLAMETTE Tract or Surv. No. Cor. 13

USDA-FOREST SERVICE

Index
File No. E-7

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____
Cor.
No. E-7


T 65 R. 33E

R.D. VK196 County _____

Merid. NIL

N.F. Vernonia State Ore.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Several Spruce in the area with
closed blazes. I did not open them.
Possible one or more are B.T.'s.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature
B. Moore

Title _____

Division _____

Headquarters _____

Date
8-79

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. U.S. G.P.O. 1977-725-576/586