

Index
File No. G-21

CORNER RECORD (SEARCH)

Tract or
Survey No. _____
Cor. No. G-21


T 6 S. R. 33 E.

R.D. UKIAH County UMATILLA

Merid. Will.

N.F. UMATILLA State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone 10" x 8" x 8", 4" above ground and in good condition. NO visible markings

Brass Cap; see Mon. File,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

11" D.B.H. LARCH BRs. S. 33° W, 37 lks. - dead

16" D.B.H. LARCH BRs. N. 25° E. 42 lks. - poor vigor

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Approximately 1200 Ft. north from forks of Cable Creek.

Signature

M. L. Christian

Title

Forestry Tech.

Division

Headquarters

UKIAH

Date

5-4-71

7100-52

REV. '65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. G-21 T. R. M. Tract or Surv. No. Cor. _____