

USDA-FOREST SERVICE

Index
File No. N-5
T 65 R. 33E
Merid. Will

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

R.D. NORTH FORK JOHN DAY County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM

T65 R33E



DESCRIBE CORNER MONUMENT FOUND

Original stone in place marked with 3 grooves on one face & 2 grooves on another at 90° to first face.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Orig 11" fir is live & now 24" WITH double healed blazes, Bears N41°E, 31.7 ft.
orig 24" pine is down. Scribes are visible on partly healed upper blaze - lower blaze healed over. Bears N30°W, 67.3 ft.
orig 40" pine is now a sawn stump with a

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

healed lower blaze, I open & find scribes "BT"
Bears S80°W, 23.1 ft.
Orig 40" pine is down, I find scribes on an unhealed blaze covered with soil from roots.
Root hole bears S40°E, 44.9 ft.
(Continued on back)

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis L. Gaylord

PLS 1636

S.O.

7-24-86

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

I put a location poster on a 14" fir N70°E, 8' from corner. There is a cedar section line board on east bank of Road 55 on a small fir, but this board is about 200 ft. East of the section line. Road 55 is 1,600 ft. South of corner

12

Index File No. T. R. M. WILL Tract or Surv. No. Cor.

N-5

65

33E

GPO : 1984 O - 439-095

13

USDA-FOREST SERVICE


Index
File No. N-5

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. Cor.
No. N-5

T 6S R. 33E R.D. Ukiah County
Merid. Williametter N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND 1

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

None: FS location poster on road south and west of area.

Corner was found 1965

PHOTO IDENTIFICATION DATA 6

Photo No.
Filed At.
Object Ident.
Ident. By
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

PLANE COORDINATE POSITION DATA 7

State Zone
X
Y
Estab. By
Agency

Signature B. Moore Title Division Headquarters Date 10/79 4
7100-52-(3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

Work Done By _____ Title _____ Date _____ State Registration No.
or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. U.S. G.P.O. 1977-725-576/586

13