

Chains

Descend through heavy timber and dense undergrowth, bears
N. 80° W. and E.

61.15 Creek, 10 lks. wide, in ravine 200 feet deep, course W.
Ascend over irregular W. slope.

73.75 Top of rise bears E. and W.
Descend along steep W. slope.

76.11 Intersect the closing cor. of secs. 18 and 19, establish-
ed by me August 7, 1901.

80.55 Intersect the cor. of secs. 13 and 24, described hereto-
fore.

Land, mountainous.

Soil, stony, 3rd and 4th rate.

Timber: Fir, pine, tamarack, spruce, alder and yew.

Undergrowth: Small firs, mountain laurel, huckleberry,
vine maple and yew.

Mountainous land, 80.55 chs.

August 13, 1901.

Retracement of
E. boundary T. 2, N., R. 36 E.

I commenced at the cor. of secs. 13, 18, 19 and 24, on
the E. bdy. of the Tp., which is a basalt stone, 18x9x6
ins., set loosely in the ground, and marked and wit-
nessed as described by the Surveyor General, with the
exception of the S.W. and N.W. bearing trees which have
been destroyed by fire, from all appearances.

I reestablished the old cor. at the same point as follows:

Set a basalt stone, 18 x 9 x 6 ins., 12 ins. in the
ground for cor. of secs. 13, 18, 19 and 24, marked with
3 notches on the S. and N. edges, from which

A fir, 8 ins. in diam. bears N. 80° E., 21 lks. dist.,
marked T. 2 N., R. 37 E., S. 18, B. T.

A fir, 12 ins. in diam., bears S. 29½° W., 46 lks.
dist., marked T. 2 N., R. 36 E., S. 24, B. T.

A fir, 7 ins. in diam. bears N. 36½° W., 47 lks.
dist., marked T. 2 N., R. 36 E., S. 13, B. T.